

Bluff Villas Regime #55, HPR

Copper Ball Valve Replacement Program

- 1.** Have your plumber install new copper ball valves on each main water supply line (hot and cold) and conspicuously label the locations.
- 2.** Submit a copy of your plumber's bill to Bluff Villas Regime #55, HPR % IMC Resort Services, Inc. for reimbursement.
- 3.** Bluff Villas Regime #55, HPR will reimburse the owner for the plumber's portion of the bill only. Any cosmetic drywall repairs are solely the responsibility of the condo owner.

Bluff Villas Regime #55, HPR
% IMC Resort Services, Inc.
2 Corpus Christi #302
Hilton Head Island, SC 29928

Attention: Bill Gephart