

Tradewinds Smoke Alarms

When we checked our smoke alarms in fall 2019, we observed they were dated with the year 2006 indicating they were the original construction smoke alarms. It is recommended that smoke alarms be replaced every 10 years.

These smoke alarms are powered by the house electrical system with a battery backup. We researched the model and found that Amazon had a 6-pack of equivalent models that would plug right in for about \$75. This included the 9-volt battery backup and we felt it was a pretty good price.

Amazon link for smoke detector 6-pack:


https://www.amazon.com/gp/product/B00ELLBAXK/ref=ppx_yo_dt_b_asin_title_o04_s00?ie=UTF8&psc=1

We replaced all our alarms (6 in total) and it took only 1-2 minutes per alarm. I am a retired engineer and enjoy working projects like this, so if anyone needs any help making the change, just let me know.

Mike Carroll

30 Trade Winds Trace Apt 3

Email: mikecarroll.hhi@gmail.com



3-wire connector
for house
electrical system



Manufacture date
(this is our new
one we installed
Oct 2019)